



Et Formation Complète Pour L'installation Imprimant **Evolis Dualys 3** Et Logiciel Création Des Badge

Contact : contact@ami-info.com

Le Service Disponible Au Maroc

{tabs type=tabs} {tab title=Windows 10} **Télécharger De Pilote Et De Logiciel Evolis Dualys 3 Pour Windows 10**

Microsoft Windows 10 (32-bit) & (64-bit)

Dualys 3 Windows 8 /10 driver

(1.92MB)

BETA version

[Télécharger](#)

{/tab}

{tab title=**Windows 7**}Télécharger De Pilote Et De Logiciel Evolis Dualys 3 Pour Windows 7

Microsoft Windows 7 (32-bit) & (64-bit)

Pilote Windows Dualys 3 (v. 4.0.1.18 - publié le 27 octobre 2010)

(1.81MB)

[Télécharger](#)

{/tab}

{tab title=**Windows 8**}Télécharger De Pilote Et De Logiciel Evolis Dualys 3 Pour Windows 8.1 & Windows 8

Microsoft Windows 8 (32-bit) & (64-bit)

Dualys 3 Windows 8 /10 driver

(1.92MB)

BETA version

[Télécharger](#)

{/tab}

{tab title=**Windows XP**}Télécharger De Pilote Et De Logiciel Evolis Dualys 3 Pour
Windows XP

Microsoft Windows XP (32-bit) & (64-bit)

Pilote Windows Dualys 3 (v. 4.0.1.18 - publié le 27 octobre 2010)

(1.81MB)

[Télécharger](#)

{/tab}

{tab title=**Windows Vista**}Télécharger De Pilote Et De Logiciel Evolis Dualys 3 Pour

Windows Vista

Microsoft Windows Vista (32-bit) & (64-bit)

Pilote Windows Dualys 3 (v. 4.0.1.18 - publié le 27 octobre 2010)

(1.81MB)

[Télécharger](#)

[Dualys 3 Firmware - v.1510 \(released on March 05, 2015\)](#)

{/tab} {/tabs}

Windows 2000 and Server 2003 drivers

The driver to be downloaded is the same than for other Windows platforms.

For Windows 2000, this setup driver has been tested successfully on x86 processor.

The compatible ports are:

USB port

Standard TCP/IP port (Ethernet) 1

Please note that no tests have been conducted with IA64 processor.

1 - The Evolis port monitor is not compatible with the Ethernet port.

For Windows 2003, this setup driver has been tested successfully on x86 processor and the x64 processor.

The compatible ports are:

USB port

Standard TCP/IP port (Ethernet) 1

Please note that no tests have been conducted with IA64 processor.

1 - The Evolis port monitor is not compatible with the Ethernet port.